

**City of Tacoma  
Hylebose Waterway Bridge**



**Elevation View**

**City of Tacoma  
Hylebose Waterway Bridge**



**Deck View**

**City of Tacoma  
Hylebose Waterway Bridge**



**Approach Deck**

**City of Tacoma  
Hylebose Waterway Bridge**




**Approach Deck Condition**

**City of Tacoma  
Hylebose Waterway Bridge**



**Approach Span Cap Deterioration**

**City of Tacoma  
Hylebose Waterway Bridge**



**Approach Pile Rot**

### **Clark County Lucia Falls Bridge**



**Elevation View**

### **Clark County Lucia Falls Bridge**



**Elevation View**

### **Clark County Lucia Falls Bridge**



**Bridge Soffit with Exposed Rebar**

### **Clark County Lucia Falls Bridge**



**Deterioration in Overhangs**

### Skagit County North Fork Bridge



Elevation View

### Skagit County North Fork Bridge



Deck View

### Skagit County North Fork Bridge



Bearing Condition

### Skagit County North Fork Bridge



Exposed Footing and Drift Accumulation

### Skagit County North Fork Bridge



Seismically Vulnerable Bearings

### Skagit County North Fork Bridge



Unstable Pier 8 – 4' Out of Plumb



**City of Bothell  
102<sup>nd</sup> Avenue Bridge**



Elevation, Looking West

**Elevation View**

**City of Bothell  
102<sup>nd</sup> Avenue Bridge**



Bridge Deck Looking South

**Deck View**

**City of Bothell  
102<sup>nd</sup> Avenue Bridge**



Bridge Deck Showing Exposed Reinforcing Bars

**Deck Condition**

**City of Bothell  
102<sup>nd</sup> Avenue Bridge**



Concrete Spall at Bearing

**Exposed Rebar**

**City of Bothell  
102<sup>nd</sup> Avenue Bridge**



Replace Existing Welded Repairs

**Welded Repair in Bottom Flange**

**City of Bothell  
102<sup>nd</sup> Avenue Bridge**



Base Girders on Pin Bearings (Bent 5)

**Seismically Vulnerable Tall Bearings**

### Grant County Crescent Bar



Elevation View

### Grant County Crescent Bar




Deck View

### Grant County Crescent Bar



Underside of bridge and Channel Bank

### Grant County Crescent Bar



Cantilevered Sidewalk

### Grant County Crescent Bar



Paint Condition

### Grant County Crescent Bar



Load Posting

## **Snohomish County South Slough Bridge**



**Elevation View**

## **Snohomish County South Slough**



**Deck View**

## **Snohomish County South Slough**



**Slough Channel**

## **Snohomish County South Slough**



**Typical Barrier Damage**

## **Snohomish County South Slough**



**Bicycle Traffic on Road**

## **Snohomish County South Slough**



**Bridge is Narrow for Truck Traffic**



**City of Chelan  
Chelan River Bridge**



**Elevation View**

**City of Chelan  
Chelan River Bridge**




**Deck View**

**City of Chelan  
Chelan River Bridge**



**Orientation to Major Intersection in Town**

**City of Chelan  
Chelan River Bridge**



**Bridge Orientation to a Lake Side Resort**

**City of Chelan  
Chelan River Bridge**



**Orientation to Lakeside Park and Trail**

**City of Chelan  
Chelan River Bridge**



**Trail on Other Side State Highway Bridge**

## **Whatcom County GN RR Overpass**



**Elevation View**

## **Whatcom County GN RR Overpass**



**Deck View**